

DEPARTMENT OF TRANSPORTATION**DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-015123**Date Inspected:** 20-Jun-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai,China**CWI Name:** Mr.Wu shi gao**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Nagalingam Pandaram Pillai was present during the times noted above for observations relative to the work being performed.

In process Inspection

Out Side

This QA Inspector observed the following work in progress:

SMAW in the 3G position for the OBG Segment 11DE , weld No. SEG072D-079. The welder is identified as #054013. ZPMC QC is identified as Mr. Tang ya jun. The welding variables recorded by QC appear to comply with WPS-B-P-2213-TC-U4b-FCM.

This QA inspector observed the following work in progress:

SMAW in the 3F position for the OBG Segment 11BE , weld No. SEG068D-007. The welder is identified as #051359. ZPMC QC is identified as Mr. Wu Zhi Guo.The welding variables recorded by QC appear to comply with WPS-B-T-4113-2.

This QA inspector observed the following work in progress:

SMAW Welding of weld joint no: SEG 068-033 located on 11BE Deck Splice Plate. Welder is identified as 200113. ZPMC CWI is identified as Mr.Wu Shi Gao. Welding was been performed against Weld Repair Report B-WR8842 and UT report number-B787-UT-9693.The welding variables recorded by QC appeared to comply

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

with the WPS-345-SMAW-4G(4F)-Repair. Please see the attached picture.

Bay #14

This QA Inspector observed the following work in progress:

SAW in the 1G position for the OBG Segment 13AE bottom Plate, weld No. BP3033-001-002. The welder is identified as #044771. ZPMC QC is identified as Mr. Guo xing Hui. The welding variables recorded by QC appear to comply with WPS-B-T-2221-B-U3c-S-2.

This QA Inspector observed the following work in progress:

FCAW in the 2F position for the OBG Segment 13AE Side Plate, weld No. SP3060E-001-011. The welder is identified as #044774. ZPMC QC is identified as Mr. Wang Xu. The welding variables recorded by QC appear to comply with WPS-B-T-2132.

This QA Inspector observed the following work in progress:

FCAW in the 2F position for the OBG Segment 13AW Side Plate, weld No. SP3092B-001-067. The welder is identified as #044830. ZPMC QC is identified as Mr. Wang Xu. The welding variables recorded by QC appear to comply with WPS-B-T-2132.

Bay #16

This QA Inspector observed the following work in progress:

SAW in the 1G position for the OBG Segment 13AW bottom Plate, weld No. BP3074-001-005. The welder is identified as #045265. ZPMC QC is identified as Mr. Xia Chun Hui. The welding variables recorded by QC appear to comply with WPS-B-T-2221-B-U3c-S-2. Please see the attached picture.

Magnetic Particle Testing:-

Bay #19

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control Personnel. This QA Inspector generated an MT report for this date. The member is identified as Suspend Brackets. The weld designation reviewed is as follows:

SB013-062-005,007,004,026,032,008,061,049,037,009,010.

SB016-070-026,032,031,043,055,037,005,008,007,004,001,011,020.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

No Relevant Conversation.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By: Pillai,Pandaram

Quality Assurance Inspector

Reviewed By: McClendon,Timothy

QA Reviewer